

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

EDR ID Number  
EPA ID Number

DB524  
ENE  
1/2-1  
0.812 mi.  
4289 ft.

CONEY ISLAND HOSPITAL  
2619 OCEAN PARKWAY  
BROOKLYN, NY

NY Spills S123661168  
N/A

Site 2 of 6 in cluster DB

Relative:  
Higher

Actual:  
9 ft.

SPILLS:

Name: CONEY ISLAND HOSPITAL  
Address: 2619 OCEAN PARKWAY  
City,State,Zip: BROOKLYN, NY  
Spill Number/Closed Date: 1811538 / 2019-06-18  
Facility ID: 1811538  
Facility Type: ER  
DER Facility ID: 534969  
Site ID: 582484  
DEC Region: 2  
Spill Cause: Unknown  
Spill Class: C4  
SWIS: 2401  
Spill Date: 2019-02-19  
Investigator: RMPIPER  
Referred To: Not reported  
Reported to Dept: 2019-02-19  
CID: Not reported  
Water Affected: Not reported  
Spill Source: Commercial/Industrial  
Spill Notifier: Other  
Cleanup Ceased: Not reported  
Cleanup Meets Std: False  
Last Inspection: Not reported  
Recommended Penalty: False  
UST Trust: False  
Remediation Phase: 0  
Date Entered In Computer: 2019-02-19  
Spill Record Last Update: 2019-06-18  
Spiller Name: HENRY GOLD 917-836-2011 CELL  
Spiller Company: CONEY ISLAND HOSPITAL  
Spiller Address: 2619 OCEAN PARKWAY  
Spiller Company: 999  
Contact Name: HENRY GOLD 917-836-2011 CELL  
DEC Memo: "2/19/19-Zhune spoke to Henry Gold 917-836-2011. Henry said they were doing construction work at Coney Island Hospital. They were doing drilling work and during drilling they encountered a subsurface structure. This morning they came to the site. They exposure the structure and excavated along the site and found a vault with a tank in. They excavated and hit the water table about 5-6' bg. and encountered odor and a sheen. They are nor sure if remove or abandon the tank in place. They need to see what the Engineer says. 2/20/19-CSL letter was sent to: Mr. Daniel Collins 2601 Ocean Parkway Brooklyn, NY 11235 5/6/19- DEC Piper- PRe-work notification received. Tank to be removed shortly. 6/17/19- DEC Piper received and reviewed closure report. Based on work to date, this spill is closed. No Further action granted. report in DEC Docs. "  
Remarks: "loss discovered during excavation, unknown type of fuel"

All Materials:

Site ID: 582484  
Operable Unit ID: 1330164  
Operable Unit: 01  
Material ID: 2339313

Map ID  
Direction  
Distance  
Elevation

MAP FINDINGS

Site

Database(s)

EDR ID Number  
EPA ID Number

Material Code:	0066A
Material Name:	unknown petroleum
Case No.:	Not reported
Material FA:	Petroleum
Quantity:	Not reported
Units:	Not reported
Recovered:	Not reported
Oxygenate:	Not reported